DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-013108 Address: 333 Burma Road **Date Inspected:** 15-Apr-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

> 34-0006 **Component:** OBG

Summary of Items Observed:

Bridge No:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

ULTRASONIC INSPECTION

OBG SEGMENT 8CE

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Weld identification numbers were.

CA054-004 (8CE- DP to EP, BP side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication. For more information refer the ABF /CT report dated on 04/13/2010 &04/15/2010.

This QA Inspector randomly observed the following work in progress.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

OBG SEGMENT 7CE

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 037743 performing Shielded Metal Arc Welding process for weld OBE7C-004 located on PCMK OBG segment 7CE. ZPMC QC Mr. Zhang Xian Ming monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-4G (4F)-FCM-Repair-1. Weld repair report identified as B-WR12035.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 058087 performing Shielded Metal Arc Welding process for weld CA039-004 located on PCMK OBG segment 7CE. ZPMC QC Mr. Wang Zhu monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-2G (2F)-FCM-Repair-1. Critical weld repair report identified as B-CWR1227-R-3.

OBG SEGMENT 7AW-7BW

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 047864 performing Shielded Metal Arc Welding process for weld SP478-001-049 located on PCMK OBG segment 7AW. ZPMC QC Mr. Wang Zhu monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-3G (3F)-FCM-Repair-1. Weld repair report identified as B-WR11909.

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer